



JPS Board of Trustees

Bond Update

June 2, 2020

Bond Construction Program - Phases II and III

Design Team Selection

Design Team:

Executive Summaries (firm recommendations) have been completed.

Contracts are being reviewed.



Facilities and Operations

Staff and Vendors Bond Project Participation

Facilities and Operations Staff and Small Local Vendors:

Facilities and Operations staff and small contractors (vendors) have performed over 30 projects under \$50,000.00 via departmental work or informal bids.

Samples of Work/Projects

- Façade Upgrades
- Interior and Exterior Lighting Upgrades
- Parking Lot Resurfacing
- Restroom Renovations
- Walkway Repairs and Improvements
- Painting Interior Corridors



MDE – Corrective Action Plan (CAP) Update

Bond Construction to Correct Deficiencies

Elementary Schools

- **Boyd Elementary School** (*Remaining Corrective Work to be Completed*)

1	Classrooms	• No second means of egress in the library computer room and speech room.
2	Classrooms	• 3rd and 4th grade classroom windows do not meet Life Safety Code.

- **Van Winkle Elementary School** (*Completed*)

1	Exterior	• Damaged back parking lot surface where buses have parked.
---	----------	---



MDE – Corrective Action Plan (CAP) Update

Bond Construction to Correct Deficiencies

Middle Schools

- **Bailey APAC Middle School** (*Remaining Corrective Work to be Completed*)

1	Gymnasium	• Damaged Bleachers.
2	Classrooms	• Second means of egress was obstructed in room 112.
3	Classrooms	• No second means of egress in rooms 108, 109 and 110.
4	Gymnasium	• No A/C in the gymnasium.



MDE – Corrective Action Plan (CAP) Update

Bond Construction to Correct Deficiencies

High Schools

- **Callaway High School** (*Remaining Corrective Work to be Completed*)

1	Classrooms	• Windows did not meet Life Safety Code.
2	Classrooms	• No second means of egress.

- **Forest Hill High School** (*Remaining Corrective Work to be Completed*)

1	Interior	• Roof leaks throughout the buildings.
2	Classrooms	• No second means of egress in rooms 125 and 132.
3	Auditorium	• Roof leaks in the stage and seating area.
4	Gymnasium	• No A/C in the Gym.
5	Gymnasium	• Gym floor not level.
6	ROTC Building Classrooms	• No second means of egress in rooms 301 and 317.



MDE – Corrective Action Plan (CAP) Update

Bond Construction to Correct Deficiencies

High Schools

- **Jim Hill High School** (*Remaining Corrective Work to be Completed*)

1	Gymnasium	• Damaged bleachers.
---	-----------	----------------------







- **Wingfield Hill High School** (*Remaining Corrective Work to be Completed*)

1	Exterior	• Water standing in the tunnel area under the school.
2	Interior	• Roof leaks throughout the buildings.
3	Halls	• Water enters the building under the East main hall exit door.
4	Classrooms	• No second means of egress in rooms 97, 98, 99, and 214. (Note: All complete except room 214.)
5	Classrooms	• Roof leaks in rooms 97, 110, 112, and choir room.
6	Classrooms	• Water stands in the Northeast corner of room 110 after a big rain.









Major Projects Under Construction

Spring and Summer 2020 – Phase I **(17 Locations)**

School/Location	March	April	May	June	July	August
Boyd Elementary School - MDE						
Green Elementary School						
Van Winkle Elementary School - MDE						
Wilkins Elementary School						
Bailey Middle School - MDE						
Hardy Middle School						

Major Projects Under Construction

Spring and Summer 2020 – Phase I (17 Locations)

School/Location	March	April	May	June	July	August
Callaway High School - MDE						
Forest Hill High School - MDE						
Jim Hill High School - MDE						
Lanier High School						
Murrah High School						
Provine High School						

Major Projects Under Construction

Spring and Summer 2020 – Phase I (17 Locations)

School/Location	March	April	May	June	July	August
Wingfield High School - MDE	■					
CDC	■					
CCAS				■		
Hughes Field				■		
South Jackson Field				■		

Line Item Projects Under Construction

Spring and Summer 2020 – Phase II (18 Locations)

School/Location	March	April	May	June	July	August
Baker Elementary School				■		
Bates Elementary School			■			
John Hopkins Elementary School				■		
Johnson Elementary School				■		
Marshall Elementary School				■		
Oak Forest Elementary School				■		

Line Item Projects Under Construction

Spring and Summer 2020 – Phase II (18 Locations)

School/Location	March	April	May	June	July	August
Pecan Park Elementary School				■		
Raines Elementary School				■		
Spann Elementary School				■		
Timberlawn Elementary School				■		
Watkins Elementary School				■		

Line Item Projects Under Construction

Spring and Summer 2020 – Phase II (18 Locations)

School/Location	March	April	May	June	July	August
Blackburn Middle School				■		
Brinkley Middle School			■			
Cardozo Middle School			■			
Chastain Middle School				■		
Northwest Middle School				■		
Powell Middle School				■		
Whitten Middle School				■		



**Before
Image**




**After
Image**

Chastain Middle School Portico and Walkway Repairs - Completed



Forest Hill High School Restroom Renovations - Under Construction





John Hopkins Elementary School Concrete Entrance Apron - Completed





Thank You

We Welcome Any Questions