

excellent education

# JPS Board of Trustees Bond Update 9.1.2020

#### Points of Interest

#### Sample Listing of Project Status

Photos of Various Projects (Completed and Under Construction)



#### **Points of Interest**

#### **Architectural Firms**

Staff has met with all newly hired Architectural firms and provided each firm the scope of work for each project and the timeline to complete each project.

#### **Bond Oversight Committee**

The Bond Oversight Committee visited two bond construction sites (Callaway and Forest Hill High Schools) and was pleased with the progress and work performed.

#### **Bond Administration Team**

Several small minority contractors are experiencing growth in their bonding compacity due to opportunities the Bond Construction Program has granted them. This was one of the Bond Administration Team's objectives.



Projects	Phase	Status
All Fields		
Hughes Field	Design	Design in progress
South Jackson Field	Bidding	Construction contract is being prepared
Baseball Complex	Design	Design in progress
Newell Field	Design	Design is progress
Forest Hill		
JROTC Building	Design	Pending M3A HVAC assessment and cost estimate review
Murrah HS		
Restroom Renovation	Contracting	Board Approved 8/18/20 construction contract is being prepared
Entry Walkway	Construction	Under Construction
Exterior Door replacement		Completed

Projects	Phase	Status
All Science Labs	Construction	Under Construction ( Murrah, Lanier, Callaway, Provine, Jim Hill)
Callaway HS		
Reroofing, HVAC and Gym	Construction	Under Construction
Bleacher Repair	Construction	On schedule (Stored away until gym floor under construction is completed
Capital City Alternative School		
Site & Drainage Repair	Construction	Under Construction
Restroom Renovation	Bidding	Construction contract is being prepared
Hardy Middle School		
Window & Door Replacement	Construction	Under Construction
Restroom Renovation	Bidding	Construction contract is being prepared



Projects	Phase	Status
Career Development Center		
Door Replacement	Construction	Under Construction
Restroom Renovation	Construction	Under Construction
Carpet Replacement		Completed
Paver Repair		Completed
Provine HS		
Restroom Renovation	Construction	Under Construction
Kitchen Plumbing Repair	Bidding	Bid Opening 9/16/20
Exterior Lighting		Completed



Projects	Phase	Status
Bailey MS		
Structural Repair	Design	Structural Engineer to provide additional reports
Wingfield		
Restroom Renovation		Completed
Sewer Line Repair		Completed
Structural Repair	Contracting	Pending Board Approval
Exterior Door Frame	Contracting	Pending Board Approval
Green ES		
All Projects	Construction	Under Construction
Boyd		
Front entry Structural repair	Construction	Completed
Egress Window & Door	Construction	Completed



Projects	Phase	Status
Forest Hill		
General Improvements	Construction	Under Construction
Coliseum Renovation	Construction	Under Construction
Restroom Renovation	Construction	Under Construction
Performance Art Space	Design	Architectural Design Ongoing
Roof Repair	Construction	Completed
Jim Hill HS		
Gym Floor & Bleacher	Construction	Under Construction
Restroom Renovation	Construction	Under Construction
Building Entry Façade Upgrade	Design	Revising Design – Requires Mississippi Dept. of Archives and History Approval



Projects	Phase	Status
Lanier HS		
Repair under Building		Completed
Restroom renovation	Construction	Under Construction
Building Entry Façade	Bidding	Pending Ad Dates
JROTC Sink Hole/Sewer repair	Bidding	Securing quotes for investigate work
Library & Academy	Bidding	Set to Bid on 8/26/20



Key Elementary
School
Façade
Upgrade
Completed








Marshall Elementary School Exterior Light Replacement Completed









Provine
High School Restroom
Renovations
Under Construction

Callaway
High School
Gym
Renovation
Under
Construction

MDE Standard 30 – Air Condition is Gymnasium Corrective Action – New air conditioning system has been installed





Callaway
High School
Interior
Upgrade
Under
Construction





# Callaway High School Window Replacement Under Construction

MDE Standard 30 – Second means of egress in classrooms Corrective Action – New windows are being installed



Forest Hill
High School
Interior Upgrade
Under Construction









# Jim Hill High School Bleacher Replacement Under Construction

MDE Standard 30 – Second means of egress in classrooms

Corrective Action - Damage

Bleacher are being Removed









Murrah High School Walkway Improvement Under Construction





Transforming lives through excellent education

**We Welcome Any Questions**